

Appn. NO. 10/000,000
Amtdt. Dated: July 20, 2007
Reply to office Action of Apr. 20, 2007
Replacement sheet #1




FIG. 1
(Prior Art)

Appin. No. 10/880,068
Amctt. Dated: July 20, 2007
Reply to office Action of April 20, 2007
Replacement Sheet #2




FIG. 2

Appln. No. 10/800,068
Amtdt. Dated: July 20, 2007
Reply to Office Action of Apr. 20, 2007
Replacement sheet #3





FIG.3

Appln. No. 10/800,068
Amtdt. Dated: July 20, 2007
Reply to Office Action of Apr. 20, 2007
Replacement sheet #4

FIG. 4



Appln. No. 10/800,068
Amtd. Dated: July 20, 2007.
Reply to office Action of Apr. 20, 2007
Replacement Sheet #5




FIG. 5

Appin. NO. 10/000,000

Amend. Dated: July 20, 2007

Reply to Office Action of Apr. 20, 2007


Replacement Sheet #6

FIG. 6

Symbol	Symbol Value	...	System Page Variable	...
...
CurrentTaskID	00000400	...	Y	...
InterruptLevel	00000404	...	Y	...
64bitTimer	00000408	...	Y	...
...

Amend. Dated: July 20, 2007
Reply to Office Action of Apr. 20, 2007
Replacement sheet # 17

FIG. 7



Appln. No. 10/800,068
Amdt. Dated: July 20, 2007
Reply to office Action of Apr. 20, 2007
Replacement Sheet #8




FIG. 8